

Amy Ow

From: Camille Leung
Sent: Tuesday, June 23, 2020 9:21 AM
To: Deke & Corrin Brown
Cc: Amy Ow
Subject: FW: Lot 11 Pre-Site Inspection 6/22/2020
Attachments: Tree Protection N Side Lot 11.JPG; Riparian Protection Fencing S side Lot 11.JPG

FYI

From: Jessica Henderson-McBean <JHenderson-McBean@swca.com>
Sent: Monday, June 22, 2020 5:47 PM
To: Camille Leung <cleung@smcgov.org>
Cc: Amy Ow <aow@smcgov.org>; Kristen Outten <koutten@swca.com>
Subject: Lot 11 Pre-Site Inspection 6/22/2020

CAUTION: This email originated from outside of San Mateo County. Unless you recognize the sender's email address and know the content is safe, do not click links, open attachments or reply.

Hi Camille,

I conducted the pre-site inspection at Lot 11 today, and the site looks great. NexGen has addressed my action items from the previous two pre-site inspections. All tree protection fencing has been installed per the civil plans and the tree protection plan. In addition, the silt fence has been installed around the limits of grading, and it has been properly keyed in.

As we discussed last week, at the initiation of ground disturbance onsite a stabilized construction entrance will need to be constructed and maintained throughout the duration of the construction activities per the erosion control plan. However, construction equipment will be required to construct the entrance, therefore it should be part of the initial construction activities onsite. I mentioned this requirement to Bob today.

Please let me know if you have any additional questions.

Jessie Henderson-McBean
Biologist

SWCA Environmental Consultants
60 Stone Pine Road, Suite 100
Half Moon Bay, CA 94019
P 650.440.4160 x 6410 | C 805.712.8794



The contents of this email and any associated emails, information, and attachments are CONFIDENTIAL. Use or disclosure without sender's authorization is prohibited. If you are not an authorized recipient, please notify the sender and then immediately delete the email and any attachments.

